

**Inspection Report**

**Report No.:** XYNK-130830  
**Supplier :** XY-GLOBAL

**Inspection Date:** 27<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

Inspection only for: PO . XYNK-130830 Item No.1380023	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1380023	2000Pcs	100% inspection	0pcs	No failure	2000Pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

物料	铝件CNC加工
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
数量	
用途	
材料	
公差	
表面处理	
包装	
交货期	
备注	
1. 物料CNC加工	
2. 物料	
物料AL6061 AL6065 AL6063 AL7075	
4. 物料	
5. 物料±0.01	
6. 物料100	
7. 物料	
8. 物料25-30	
9. 物料	
10. 物料	
11. 物料ISO 9001	
物料	
1.10. 物料ISO	
2. 物料	
3. 物料	
4. 物料	
5. 物料	
6. 物料	
7. 物料	
物料	
物料	
物料	
物料ISO9001	
物料	
物料OEM	