

**Inspection Report**

Report No.: XYKS-140605  
 Supplier: XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
 Inspector: Leo

Inspection only for: PO . XYSK-140605 Item No. XY31SY50	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY50	6000PCS	1% inspection	0pcs	No failure	6000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product
------------	------------



3. Product	4 Product
------------	-----------

	<p><b>XY-GLOBAL</b> 深圳市真朴电子科技有限公司          XY Electronics Technology Co., Ltd</p> <p>Inspection Report</p> <table border="1"> <tr> <td>Product Name: XY31SY50</td> <td>Product Type: XY31SY50</td> <td>Inspection Date: 20140702</td> <td>Inspector: Leo</td> </tr> <tr> <td>PO: XYSK-140605</td> <td>Item No: XY31SY50</td> <td>Quantity: 6000</td> <td>Lot No: 14060501</td> </tr> </table> <p>Inspection Result: PASS</p> <p>Inspection Method: 100% Inspection</p> <p>Inspection Location: XY Electronics Technology Co., Ltd</p> <p>Inspection Time: 20140702</p> <p>Inspection Status: PASS</p> <p>Inspection Report No: XYKS-140605</p> <p>Inspection Report Date: 20140702</p> <p>Inspection Report Version: 1.0</p> <p>Inspection Report Author: Leo</p> <p>Inspection Report Approver: Leo</p>	Product Name: XY31SY50	Product Type: XY31SY50	Inspection Date: 20140702	Inspector: Leo	PO: XYSK-140605	Item No: XY31SY50	Quantity: 6000	Lot No: 14060501
Product Name: XY31SY50	Product Type: XY31SY50	Inspection Date: 20140702	Inspector: Leo						
PO: XYSK-140605	Item No: XY31SY50	Quantity: 6000	Lot No: 14060501						

5. Product:	6. report
-------------	-----------



Safety is our serious job for our worker and engineer team

