

Inspection Report

Report No.: XYI-140307
 Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2014
 Inspector: Leo

Inspection only for: PO . XYI-140307 Item No.140207	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140207	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:
	
7. Product:	8. Report:

品名	精密加工品 (OEM)
品番	ADC12 A380
仕様	
公差	
材料	
製造方法	CNC
仕様書	gague
公差	
公差	+/-0.01
公差	T / T 50 50 T / T
公差	
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	

- | | |
|-----------------|------------------|
| 1.Name | |
| 2.Process | |
| | ADC12 A380 |
| 4. | |
| 5.Tolerance | ±0.01 |
| 6. | 100 |
| 7.Specification | serice |
| 8. | 25-30 |
| 9. | accessoried |
| 10. | Austrial |
| 11&NBSP; | ISO 9001 |
| | |
| 1. | 10 ISO |
| 2. | |
| 3. | kindls available |
| 4. | |
| 5. | |
| 6. | |
| 7. | |
| | |
| | NBSP; |
| | |
| | ISO9001 |
| | |
| | OEM |