

Inspection Report

Report No.: XYSK-140610
 Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140610 Item No. XY31SY010	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY010	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



