

Inspection Report






Report No.: XYNK-130810
 Supplier : XY-GLOBAL

Inspection Date: 2th Sep-, 2013
 Inspector: LEO

Inspection only for: PO . XYNK-130810 Item No.400-10-454	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-454	5000PCS	100% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

