

Inspection Report

Report No.: XYN-140602
Supplier : XY-GLOBAL

Inspection Date: 1th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140602 Item No.201978	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
201978	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
加工	&NBSP;加工品
品名	CNC加工品
品名	gague
品名	
公差	+/-0.01
公差	T / T 50 50 T / T
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name CNC加工品	
2.Process	
AL6061 AL6065 AL6063 AL7075	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.CNC accessoried	
10.Austrial	
11.&NBSP; ISO 9001	
品名	
1.10 ISO	
2.	
3.kinds available	
4.	
5.	
6.	
7.	
品名	
&NBSP;加工品	
品名	
品名 ISO9001	
品名	
品名	