

### Inspection Report

**Report No.:** XYN-140625  
**Supplier :** XY-GLOBAL

**Inspection Date:** 19<sup>th</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYN-140625 Item No.357091	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
357091	25000PCS	1% inspection	0pcs	No failure	25000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

