

Inspection Report

Report No.: XYF-130830
 Supplier : XY-GLOBAL

Inspection Date:29th Sep, 2013
 Inspector:LEO

Inspection only for: PO . XYF-130830 Item No. 2543100	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2543100	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product
3. Product:	4. Product:
5. Product :	6. inspection reports

0000	0000000CNC000000000000CNC00
00	000 AL6061 AL60650AL60630AL70750SUS3040SUS3030SUS3160
00	00000000
0000	000000000000000000000000
00	0000000000
0000	0000000000000000000000000000 0000
0000	00
000000	00000000
00/00	+/-0.0100
0000	000005000000000000000005000000
0000	00
00	00000000000000000000000000000000000000
00	000000
00	0000005000000250000
0000	00000000
1.0000000000CNC00	
2.0000000000000000	
000000AL6061 AL60650AL60630AL70750	
4.0000000000000000 0000	
5.000000±0.0100	
6.000000100000	
7.0000000000000000000000	
8.00000025-3000	
9.0000000000000000 00000000000000	
10.00000000000000000000	
11000000000ISO 9001	
000000	
1.10000000ISO00	
2.0000000000000000	
3.0000000000000000	
4.000000000000	
5.000000	
6.000000	
7.00000000000000	
000000	
0000000000000000000000	
00000000000000	
00000000000ISO9001	
000000000000000000	
00OEM00000000	