

**Inspection Report**

**Report No.:** XYBA-141110  
**Supplier :** XY-GLOBAL

**Inspection Date:** 12<sup>th</sup> Dec-, 2014  
**Inspector:**LEO

Inspection only for: PO .XYBA-141110      Item No. XY21ZC027	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC027	3000Set	7% inspection	Opes	No failure	3000Set

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

