

Inspection Report

Report No.: XYN-131114
Supplier : XY-GLOBAL

Inspection Date: 4th Dec-, 2013
Inspector:KEN

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYN-131114 Item No.XY-MST-030 | <u>Inspection Result:</u> PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY-MST-030 | 25000PCS | 1% inspection | 0pcs | No failure | 25000pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

| | |
|--------------------------------|---|
| 品名 | 品名、品番、CNC加工品名、CNC加工機名、CNC加工機名 |
| 材質 | AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316 |
| 色 | 色 |
| 公差 | 公差 |
| 表面処理 | 表面処理 |
| 加工機 | CNC加工機 |
| 加工機名 | 加工機名gague |
| 加工機型 | 加工機型 |
| 公差/寸 | +/-0.01 |
| 公差 | T / T 50 50 T / T |
| 公差 | 公差 |
| 公差 | 公差 |
| 公差 | T / T 50 20-25 NBSP |
| 公差 | 公差 |
| 1. Name 品名cnc | |
| 2. Process 加工 | |
| 品名 AL6061 AL6065 AL6063 AL7075 | |
| 4. 公差 | |
| 5. Tolerance 公差±0.01 | |
| 6. 公差100 | |
| 7. Specification 仕様serice | |
| 8. 公差25-30 | |
| 9. 公差accessoried | |
| 10. 公差Austrial | |
| 11 &NBSP; 公差ISO 9001 | |
| 品名 | |
| 1 公差ISO | |
| 2 公差 | |
| 3 公差kinds available | |
| 4 公差 | |
| 5 公差 | |
| 6 公差 | |
| 7 公差 | |
| 公差 | |
| 公差 &NBSP; 公差 | |
| 公差 | |
| 公差ISO9001 | |
| 公差 | |
| 公差 | |