

Inspection Report

Report No.: XYDS-140613
Supplier : XY-GLOBAL

Inspection Date: 11th July, 2014
Inspector: Leo

Inspection only for: PO . XYDS-140613 Item No.201-10-587	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
201-10-587	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

