

Inspection Report







Report No.: XYSL-150719
 Supplier : XY-GLOBAL

Inspection Date: 22nd Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150719 Item No. XY31XL039	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL039	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	铝合金CNC加工零件CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	定制
数量	10000
公差	±0.01
表面处理	阳极氧化
包装	泡沫箱
交货期	5-7天
付款方式	预付30%
最小起订量	1000
交货地点	深圳
联系人	李经理
联系电话	13826412345
电子邮箱	li@alparts.com
1. 铝合金CNC加工	
2. 定制服务	
材料 AL6061 AL6065 AL6063 AL7075	
4. 公差 ±0.01	
5. 表面处理 ±0.01	
6. 数量 10000	
7. 交货期 5-7天	
8. 包装 25-30个	
9. 付款方式 预付30%	
10. 交货地点 深圳	
11. 认证 ISO 9001	
品名	
1.10 铝合金ISO	
2. 定制服务	
3. 表面处理	
4. 数量	
5. 公差	
6. 交货期	
7. 包装	
品名	
铝合金CNC加工零件	
品名	
铝合金ISO9001	
品名	
OEM服务	

Safety is our serious job for our worker and engineer team

