

Inspection Report

Report No.: XYKB-140518
 Supplier : XY-GLOBAL






Inspection Date: 12th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140518 Item No. XY72YM014	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM014	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report:

