

Inspection Report

Report No.: XYKB-140509
Supplier : XY-GLOBAL

Inspection Date: 4th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140509 Item No. XY72YM005	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM005	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

									
1. Packing	2. Product								
									
3. Product	4 Product								
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Inspection Part: XY72YM005</td> <td>Product Type: XY72YM005</td> <td>Inspection Date: 2014-06-04</td> <td>Inspector: Leo</td> </tr> <tr> <td>Quantity: 8000PCS</td> <td>Sample Size: 20PCS</td> <td>Defect Found: 0</td> <td>Result: PASS</td> </tr> </table> <p>Inspection results: All items passed inspection.</p> <p>Inspector: Leo</p> <p>Date: 2014-06-04</p>	Inspection Part: XY72YM005	Product Type: XY72YM005	Inspection Date: 2014-06-04	Inspector: Leo	Quantity: 8000PCS	Sample Size: 20PCS	Defect Found: 0	Result: PASS
Inspection Part: XY72YM005	Product Type: XY72YM005	Inspection Date: 2014-06-04	Inspector: Leo						
Quantity: 8000PCS	Sample Size: 20PCS	Defect Found: 0	Result: PASS						
5. Product:	6. Dimensions report:								

