

OEM□□□□



**XY Electronics Technology Co., Ltd**

**Inspection Report**

**Report No.:** XYK-130811  
**Supplier :** XY-GLOBAL

**Inspection Date:**01<sup>th</sup> Sep-, 2013  
**Inspector:**LEO

Inspection only for: PO . XYK-130811      Item No.1322100	<u>Inspection Result:</u> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
13222100	20PCS	100% inspection	0pcs	No failure	20pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

