

Inspection Report

Report No.: XYKB-140519
 Supplier : XY-GLOBAL







Inspection Date: 14th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140519 Item No. XY72YM015	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM015	1000PCS	1% inspection	Opes	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report:

