

**Inspection Report**

**Report No.:** XYNK-130813  
**Supplier :** XY-GLOBAL

**Inspection Date:** 15<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

Inspection only for: PO . XYNK-130813    Item No.7028190	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
7028190	5000PCS	100% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

