

Inspection Report

Report No.: XYS-140306
Supplier : XY-GLOBAL

Inspection Date: 2th Apr, 2014
Inspector: Leo

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYS-140306 Item No. 1000864 | Inspection Result: PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 1000864 | 8000PCS | 1% inspection | 0pcs | No failure | 8000pcs |

| |
|--|
| Appearance Inspection : |
| No failure. |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|--|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4. Product |
|  |  |
| 5. Product: | 6. Product: |

| | |
|-----------------|------------------|
| 品名 | ADC12 A380 OEM |
| 品番 | ADC12 A380 |
| 仕様 | |
| 数量 | |
| 単位 | |
| 材質 | |
| 公差 | +/-0.01 |
| 表面処理 | T / T 50 |
| 検査方法 | |
| 納入期 | |
| 備考 | |
| 1.Name | ADC12 A380 |
| 2.Process | |
| 3.品番 | ADC12 A380 |
| 4.仕様 | |
| 5.Tolerance | ±0.01 |
| 6.数量 | 100 |
| 7.Specification | serice |
| 8.納入期 | 25-30 |
| 9.付属品 | accessoried |
| 10.検査方法 | Austrial |
| 11.&NBSP; | ISO 9001 |
| 備考 | |
| 1.納入期 | ISO |
| 2.品番 | |
| 3.仕様 | kindls available |
| 4.数量 | |
| 5.単位 | |
| 6.材質 | |
| 7.表面処理 | |
| 備考 | |
| 8.&NBSP; | |
| 9.検査方法 | ISO9001 |
| 10.納入期 | |
| 11.&NBSP; | OEM |