

Inspection Report

Report No.: XYKB-140514
Supplier : XY-GLOBAL

Inspection Date: 11th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140514 Item No. XY72YM010	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM010	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :													
													
1. Packing	2. Product												
													
3. Product	4 Product												
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Client: XYKB-140514</td> <td>Product Name: XY72YM010</td> <td>Inspection Date: 2014.6.11</td> <td>Inspector: Leo</td> </tr> <tr> <td>Project: XYKB-140514</td> <td>Lot No: XY72YM010</td> <td>Customer Name: XY-GLOBAL</td> <td>Customer Code: XY72YM010</td> </tr> <tr> <td>Inspector: Leo</td> <td>Inspector Code: XY72YM010</td> <td>Inspector Code: XY72YM010</td> <td>Inspector Code: XY72YM010</td> </tr> </table>	Client: XYKB-140514	Product Name: XY72YM010	Inspection Date: 2014.6.11	Inspector: Leo	Project: XYKB-140514	Lot No: XY72YM010	Customer Name: XY-GLOBAL	Customer Code: XY72YM010	Inspector: Leo	Inspector Code: XY72YM010	Inspector Code: XY72YM010	Inspector Code: XY72YM010
Client: XYKB-140514	Product Name: XY72YM010	Inspection Date: 2014.6.11	Inspector: Leo										
Project: XYKB-140514	Lot No: XY72YM010	Customer Name: XY-GLOBAL	Customer Code: XY72YM010										
Inspector: Leo	Inspector Code: XY72YM010	Inspector Code: XY72YM010	Inspector Code: XY72YM010										
5. Product:	6. Dimensions report:												

