

Inspection Report

Report No.: XYF-130819
Supplier : XY-GLOBAL

Inspection Date: 11th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYF-130819 Item No. screw cap	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
screw cap	8000Set	100% inspection	0pcs	No failure	8000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

項目	鋁合金CNC加工品CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	各種形状
用途	機械部品、構造部品、金型など
加工	各種加工
公差	0.01mm～0.05mm
表面	各種表面処理、研磨など
検査	各種検査
納期	約1～2週間
送料	別途見積
お問い合わせ	お問い合わせ
項目	+
公差	+/-0.01mm
用途	機械部品、構造部品、金型など
加工	各種加工
形状	各種形状
用途	機械部品、構造部品、金型など
加工	各種加工
公差	0.01mm～0.05mm
表面	各種表面処理、研磨など
検査	各種検査
納期	約1～2週間
送料	別途見積
お問い合わせ	お問い合わせ
項目	1. 鋁合金CNC加工品
項目	2. 鋁合金CNC加工品
項目	AL6061 AL6065 AL6063 AL7075
項目	4. 各種加工
項目	5. 公差 +/-0.01mm
項目	6. 公差 100mm
項目	7. 各種加工
項目	8. 公差 25-30mm
項目	9. 各種加工
項目	10. 各種加工
項目	11. ISO 9001
項目	各種加工
項目	1.10 ISO
項目	2. 各種加工
項目	3. 各種加工
項目	4. 各種加工
項目	5. 各種加工
項目	6. 各種加工
項目	7. 各種加工
項目	各種加工
項目	各種加工
項目	各種加工
項目	ISO9001
項目	各種加工
項目	OEM