

**Inspection Report**

Report No.: XYI-140322  
 Supplier : XY-GLOBAL

Inspection Date: 19<sup>th</sup> Apr, 2014  
 Inspector: Leo

Inspection only for: PO . XYI-140322 Item No.143045	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
143045	6000PCS	1% inspection	0pcs	No failure	6000pcs

**Appearance Inspection :**  
 No failure.

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

**Digital photo records :**



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:



7. Product:

8. Report:

品名	高精度デジタルゲージOEM部品
品番	ADC12-A380
仕様	
材質	ステンレス
加工	CNC加工
公差	±0.01mm
表面処理	鏡面研磨
検査	100%
納期	25-30日
備考	accessories
規格	Austrian
認証	ISO 9001
備考	
1.Name	高精度デジタルゲージ
2.Process	CNC加工
	ADC12-A380
4.	
5.Tolerance	±0.01mm
6.	100%
7.Specification	serice
8.	25-30日
9.	accessories
10.	Austrian
11.	ISO 9001
1.	ISO
2.	
3.	kindls available
4.	
5.	
6.	
7.	
	NBSP;
	ISO9001
	OEM