

Inspection Report

Report No.: XYSL-150711
 Supplier : XY-GLOBAL



Inspection Date: 19th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150711 Item No. XY31XL031	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL031	32000PCS	1% inspection	0pcs	No failure	32000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
表面処理	
検査	
納期	
備考	
1. 公差	+/-0.01
2. 公差	50
3. 公差	
4. 公差	
5. 公差	
6. 公差	50
7. 公差	25
8. 公差	
9. 公差	
10. 公差	
11. 公差	ISO 9001
1.10. 公差	ISO
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
公差	
公差	
公差	
公差	ISO9001
公差	
公差	OEM

Safety is our serious job for our worker and engineer team

