

□□□□□□□□

**Inspection Report**

**Report No.:** XYS-130630  
**Supplier :** XY-GLOBAL

**Inspection Date:** 1<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130706 Item No.XY-1301483	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-131483	<b>100PCS</b>	5% inspection	0pcs	No failure	100pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査	
納期	
備考	
1.Name	
2.Process	
	ADC12 A380
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
1	10 ISO
2	
3	kindls available
4	
5	
6	
7	
	NBSP;
	ISO9001
	OEM