

Inspection Report

Report No.: XYKI-140314
Supplier : XY-GLOBAL

Inspection Date: 15th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYKI-140314 Item No.3500097	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3500097	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

