

□□□□□□□□ADC12□□□□□

### Inspection Report






**Report No.:** XYS-130928  
**Supplier :** XY-GLOBAL

**Inspection Date:** 25<sup>th</sup> Oct, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130920 Item No.3240100	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3240100	3000PCS	5% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査	
包装	
納期	20-25 T / T 50
備考	
1.Name	
2.Process	
ADC12 A380	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.accessoried	
10.Austrial	
11. ISO 9001	
1. ISO	
2.	
3.kinds available	
4.	
5.	
6.	
7.	
NBSP;	
ISO9001	
OEM	