

**Inspection Report**

Report No.: XYSL-150716  
 Supplier : XY-GLOBAL

Inspection Date: 22<sup>th</sup> Aug, 2015  
 Inspector: Leo

Inspection only for: PO . XYSL-150716 Item No. XY31XL036	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL036	8000PCS	1% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

項目	CNC加工 CNC加工
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	任意形状
加工内容	切削加工 研磨加工
公差	任意公差
表面処理	表面研磨加工 表面防錆加工
検査	任意検査
単位	+/-0.01mm
加工時間	任意50分 任意50分
保管	任意保管
送料	任意送料
納期	任意納期
数量	任意数量
備考	任意備考
1. CNC加工	
2. 任意加工	
材料 AL6061 AL6065 AL6063 AL7075	
4. 任意加工 任意加工	
5. 任意加工 +/-0.01mm	
6. 任意加工 100mm	
7. 任意加工 任意加工	
8. 任意加工 25-30mm	
9. 任意加工 任意加工 任意加工	
10. 任意加工 任意加工	
11. ISO 9001	
任意加工	
1.10. ISO加工	
2. 任意加工 任意加工	
3. 任意加工 任意加工	
4. 任意加工 任意加工	
5. 任意加工	
6. 任意加工	
7. 任意加工 任意加工	
任意加工	
任意加工 任意加工 任意加工	
任意加工 任意加工	
ISO 9001	
任意加工 任意加工 任意加工	
OEM加工 任意加工	

Safety is our serious job for our worker and engineer team

