

**Inspection Report**

Report No.: XYF-130829  
 Supplier : XY-GLOBAL

Inspection Date: 26<sup>th</sup> Sep, 2013  
 Inspector: LEO

Inspection only for: PO . XYF-130829      Item No. 800-20-450	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
800-20-450	20000Set	100% inspection	0pcs	No failure	20000Set

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
用途	
仕様	
公差	
表面処理	
検査	
包装	
納期	
価格	
送料	
備考	
単位	+/-0.01mm
最小ロット	50個
最大ロット	500個
納期	
品質	
保証	
お問い合わせ	
1.	CNC加工
2.	
3.	AL6061 AL6065 AL6063 AL7075
4.	
5.	±0.01mm
6.	100個
7.	
8.	25-30日
9.	
10.	
11.	ISO 9001
1.10	ISO
2.	
3.	
4.	
5.	
6.	
7.	
	ISO9001
	OEM