

Inspection Report

Report No.: XYF-130814
Supplier : XY-GLOBAL

Inspection Date: 6th Sep-, 2013
Inspector: LEO

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYF-130814 Item No. screw | Inspection Result: PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| screw | 10000Set | 100% inspection | 0pcs | No failure | 10000Set |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. inspection reports |

| | |
|--------------------------------|--|
| 材名 | CNC加工品 |
| 材種 | AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 |
| 寸法 | |
| 用途 | |
| 公差 | |
| 表面粗度 | |
| 検査 | |
| 検査 | |
| 検査 | |
| 検査 | |
| 検査 | |
| 公差 | +/-0.01 |
| 公差 | 50mm以内 |
| 公差 | |
| 公差 | |
| 公差 | |
| 公差 | |
| 公差 | 50mm以内 |
| 公差 | 25mm以内 |
| 公差 | |
| 1. CNC加工 | |
| 2. 加工品 | |
| 材種 AL6061 AL6065 AL6063 AL7075 | |
| 4. 加工品 | |
| 5. 公差 ±0.01 | |
| 6. 公差 100mm | |
| 7. 公差 | |
| 8. 公差 25-30mm | |
| 9. 加工品 | |
| 10. 加工品 | |
| 11. ISO 9001 | |
| 加工 | |
| 1.10 ISO | |
| 2. 加工品 | |
| 3. 加工品 | |
| 4. 加工品 | |
| 5. 加工 | |
| 6. 加工 | |
| 7. 加工 | |
| 加工 | |
| 加工 | |
| 加工 | |
| 加工 ISO9001 | |
| 加工 | |
| OEM加工 | |