

**Inspection Report**

Report No.: XYKB-140512  
 Supplier : XY-GLOBAL

Inspection Date: 8<sup>th</sup> Jun, 2014  
 Inspector: Leo

|   |  |
|---|--|
| Inspection only for:<br>PO . XYKB-140512 Item No. XY72YM008 | <u>Inspection Result:</u><br><b>PASS</b> |
|---|--|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY72YM008   | 6000PCS       | 1% inspection | 0pcs         | No failure          | 6000pcs         |




**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

|   |   |
|---|---|
|   |  |
| 1. Packing  | 2. Product  |
|  |  |
| 3. Product  | 4 Product   |
|  |  |
| 5. Product:   | 6. Dimensions report:   |

