

**Inspection Report**

**Report No.:** XYNK-130809  
**Supplier :** XY-GLOBAL

**Inspection Date:**14<sup>th</sup> Sep-, 2013  
**Inspector:**LEO

Inspection only for: PO . XYNK-130809 Item No.400-10-200	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-200	3000PCS	100% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
表面処理	
検査	
納期	
備考	
1. 公差	+/-0.01
2. 公差	50
3. 公差	
4. 公差	
5. 公差	
6. 公差	50
7. 公差	25
8. 公差	
9. 公差	
10. 公差	
11. 公差	ISO 9001
1.10. 公差	ISO
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
公差	
公差	
公差	
公差	ISO9001
公差	
公差	OEM