

**Inspection Report**

**Report No.:** XYDN-140625  
**Supplier :** XY-GLOBAL

**Inspection Date:** 19<sup>th</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYDN-140625    Item No.357990	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
357990	2500PCS	1% inspection	0pcs	No failure	2500pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

品名	汎用CNC加工品汎用CNC
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	汎用加工品
用途	汎用加工品
公差	汎用加工品
表面処理	汎用加工品
検査	汎用加工品
納期	汎用加工品
価格	汎用加工品
備考	汎用加工品
1. 汎用加工品CNC	
2. 汎用加工品	
汎用加工品AL6061 AL6065 AL6063 AL7075	
4. 汎用加工品	
5. 汎用加工品±0.01	
6. 汎用加工品100	
7. 汎用加工品	
8. 汎用加工品25-30	
9. 汎用加工品	
10. 汎用加工品	
11. 汎用加工品ISO 9001	
汎用加工品	
1.10. 汎用加工品ISO	
2. 汎用加工品	
3. 汎用加工品	
4. 汎用加工品	
5. 汎用加工品	
6. 汎用加工品	
7. 汎用加工品	
汎用加工品	
汎用加工品	
汎用加工品	
汎用加工品ISO9001	
汎用加工品	
汎用加工品	
汎用OEM加工品	