



Inspection Report

Report No.: XYD-131025
 Supplier : XY-GLOBAL

Inspection Date:19th Nov-, 2013
 Inspector:ALEX

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYD-131025 Item No.XY-MST-082 | <u>Inspection Result:</u> PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY-MST-082 | 80000PCS | 1% inspection | 0pcs | No failure | 80000pcs |

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

| | |
|-----------------|--|
| 品名 | CNC加工品 |
| 材質 | AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 |
| 仕様 | |
| 公差 | ±0.01 |
| 表面処理 | バリ取り |
| 検査 | 寸法検査 |
| 納期 | 約1週間 |
| 送料 | 別途見積 |
| 備考 | |
| 1.Name | CNC加工品 |
| 2.Process | |
| 3.材料 | AL6061 AL6065 AL6063 AL7075 |
| 4.公差 | ±0.01 |
| 5.Tolerance | ±0.01 |
| 6.表面処理 | バリ取り |
| 7.Specification | serice |
| 8.検査 | 25-30 |
| 9.付属品 | accessories |
| 10.規格 | Austrial |
| 11. | ISO 9001 |
| 品名 | |
| 1.規格 | ISO |
| 2.仕様 | |
| 3.種類 | kindls available |
| 4.公差 | |
| 5.表面処理 | |
| 6.検査 | |
| 7.付属品 | |
| 品名 | |
| 公差 | ±0.01 |
| 検査 | |
| 規格 | ISO9001 |
| 仕様 | |
| 備考 | |