

### Inspection Report

**Report No.:** XYI-140317  
**Supplier :** XY-GLOBAL

**Inspection Date:** 13<sup>th</sup> Apr, 2014  
**Inspector:** Leo

Inspection only for: PO . XYI-140317 Item No.142150	<u>Inspection Result:</u> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142150	20000PCS	1% inspection	Opcs	No failure	20000pcs

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**


The inspection sample plan is 100% inspection.

**Digital photo records :**




1. Packing

2. Product



3. Product

4 Product



po dm is		4000-D1-1000		Rev. 01	01/09/14
Part No.	Part Name	Rev.	Quantity	Unit Price	Total Price
4000-D1-1000	4000-D1-1000	01	1000	0.8000	800.0000
4000-D1-1000	4000-D1-1000	01	1000	0.8000	800.0000
4000-D1-1000	4000-D1-1000	01	1000	0.8000	800.0000
4000-D1-1000	4000-D1-1000	01	1000	0.8000	800.0000
4000-D1-1000	4000-D1-1000	01	1000	0.8000	800.0000

5. Product:

6. Report:

品名	ステンレス鋼製 各種規格品 OEM 対応品
品番	ADC12 A380
材質	ステンレス鋼
仕様	各種規格品
加工	CNC 加工
公差	±0.01
表面処理	各種加工
検査	各種検査
納期	約 25-30 日
備考	各種規格品
1.Name	品名
2.Process	加工
3	ADC12 A380
4	各種規格品
5.Tolerance	±0.01
6	100
7.Specification	各種規格品
8	25-30
9	accessories
10	Austrial
11	ISO 9001
備考	
1	ISO
2	
3	kindls available
4	
5	
6	
7	
備考	
	NBSP;
	ISO9001
	OEM