



Inspection Report

Report No.: XYF-130824
Supplier : XY-GLOBAL

Inspection Date:19th Sep-, 2013
Inspector:LEO

Table with 2 columns: Inspection only for (PO . XYF-130824 Item No. XY-MST-089) and Inspection Result: (PASS)

Table with 6 columns: Description, Finished Q'ty, Sample Size, Defect Found, Defects Description, Acceptable Q'ty. Row 1: XY-MST-089, 30000Set, 100% inspection, Opcs, No failure, 30000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing 2. Product:



3. Product: 4. Product:



5. Product : 6. inspection reports

