

Preicse

**Inspection Report**

Report No.: XYS-130313  
 Supplier : XY-GLOBAL

Inspection Date: 12<sup>th</sup> Apr, 2013  
 Inspector: Leo

Inspection only for: PO . XYS-130313 Item No.XY-1300260	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300260	1000PCS	5% inspection	0pcs	No failure	1000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
備考	
材質	
公差	±0.01
表面処理	T / T 50
検査	
梱包	
納期	
備考	
1.Name	ADC12 A380
2.Process	
3.品番	ADC12 A380
4.公差	±0.01
5.Tolerance	±0.01
6.表面処理	T / T 50
7.Specification	
8.検査	
9.梱包	
10.備考	
11.&NBSP;	ISO 9001
品名	
1.品番	ISO
2.仕様	
3.種類	kindls available
4.数量	
5.単位	
6.備考	
7.検査	
品名	
品番	&NBSP;
仕様	
数量	ISO9001
単位	
備考	OEM