

Inspection Report

Report No.: XYN-140615
 Supplier : XY-GLOBAL

Inspection Date: 9th July, 2014
 Inspector: Leo

Inspection only for: PO . XYN-140615 Item No.140078	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140078	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6 Product
	
7. Product:	8. Report:

品名	加工機材 CNC 加工機材 CNC 加工機材 CNC
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
用途	
加工	
加工機材	CNC
加工機材	gague
加工機材	
加工機材	+/-0.01
加工機材	T / T 50 50 T / T
加工機材	
加工機材	
加工機材	T / T 50 20-25 NBSP
加工機材	
1.Name 加工機材 CNC	
2.Process	
加工機材 AL6061 AL6065 AL6063 AL7075	
4.加工機材	
5.Tolerance ±0.01	
6.加工機材 100	
7.Specification serice	
8.加工機材 25-30	
9.加工機材 accessoried	
10.加工機材 Austrial	
11&NBSP; ISO 9001	
加工機材	
1.加工機材 ISO	
2.加工機材	
3.加工機材 kinds available	
4.加工機材	
5.加工機材	
6.加工機材	
7.加工機材	
加工機材	
加工機材 &NBSP; 加工機材	
加工機材	
加工機材 ISO9001	
加工機材	
加工機材	