

Inspection Report

Report No.: XYNK-130820
Supplier : XY-GLOBAL

Inspection Date:16th Sep-, 2013
Inspector:LEO

| | |
|---|-----------------------------------|
| Inspection only for: PO .XYNK-130820 Item No.1320087 | <u>Inspection Result:</u> PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 1320087 | 500PCS | 100% inspection | 0pcs | No failure | 500pcs |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

