

Inspection Report






Report No.: XYN-131107
Supplier : XY-GLOBAL

Inspection Date: 2th Dec-, 2013
Inspector:KEN

Inspection only for: PO . XYN-131107 Item No.XY-MST-023	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-023	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	品名 品名 品名 CNC 品名 CNC 品名 品名
品名	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316 品名
品名	品名
品名	品名 品名
品名	品名
品名	CNC 品名 品名 品名
品名	品名 gague 品名 品名 品名 品名 品名
品名	品名
品名	+/-0.01
品名	T / T 50 品名 50 T / T 品名
品名	品名 品名 品名 品名 品名
品名	品名 品名 品名 品名
品名	品名
品名	T / T 50 品名 20-25 NBSP
品名	品名
1.Name 品名 cnc 品名	
2.Process 品名	
品名 AL6061 AL6065 AL6063 AL7075 品名	
4.品名 品名	
5.Tolerance 品名 ±0.01	
6.品名 100 品名	
7.Specification 品名 serice 品名	
8.品名 25-30 品名	
9.品名 品名 品名 品名 品名 品名 品名	
10.品名 品名 品名 品名 品名	
11&NBSP; 品名 ISO 9001	
品名 品名	
1.品名 10 品名 ISO 品名	
2.品名 品名	
3.品名 品名 kinds 品名 available	
4.品名 品名	
5.品名 品名	
6.品名 品名	
7.品名 品名 品名	
品名 品名	
品名 &NBSP; 品名 品名 品名	
品名 品名 品名	
品名 品名 ISO9001	
品名 品名 品名 品名	
品名 品名 品名	