

Inspection Report

Report No.: XYAK-150406
 Supplier : XY-GLOBAL

Inspection Date: 10th May, 2015
 Inspector: Leo

Inspection only for: PO . XYAK-150406 Item No. XY31AL005	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL005	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品 CNC加工品
品番	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	標準仕様
材質	標準仕様
寸法	標準仕様
公差	標準仕様
表面処理	標準仕様
検査	標準仕様
包装	標準仕様
納期	標準仕様
価格	標準仕様
備考	標準仕様
1.	CNC加工品
2.	標準仕様
3.	AL6061 AL6065 AL6063 AL7075
4.	標準仕様
5.	± 0.01
6.	100
7.	標準仕様
8.	25-30
9.	標準仕様
10.	標準仕様
11.	ISO 9001
品名	
1.10	ISO
2.	標準仕様
3.	標準仕様
4.	標準仕様
5.	
6.	
7.	
品名	
品番	
仕様	
材質	
寸法	
公差	
表面処理	
検査	
包装	
納期	
価格	
備考	
OEM	

Safety is our serious job for our worker and engineer team

