

**Inspection Report**

Report No.: XYSK-140625  
Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> July, 2014  
Inspector: Leo

Inspection only for: PO . XYSK-140625    Item No. XY31SY021	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY021	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



**XY-GLOBAL** 深圳市真朴电子科技有限公司  
XY Electronics Technology Co., Ltd

Drawn	Checked	Designed	Reviewed	Approved	Date
LEI	LEI	LEI	LEI	LEI	2014.07.15

  

NO.	DESCRIPTION	DATE	STATUS
1	Initial Release	2014.07.15	OK
2	First Change	2014.07.15	OK
3	Second Change	2014.07.15	OK
4	Third Change	2014.07.15	OK
5	Fourth Change	2014.07.15	OK
6	Fifth Change	2014.07.15	OK
7	Sixth Change	2014.07.15	OK
8	Seventh Change	2014.07.15	OK
9	Eighth Change	2014.07.15	OK
10	Ninth Change	2014.07.15	OK
11	Tenth Change	2014.07.15	OK
12	Eleventh Change	2014.07.15	OK
13	Twelfth Change	2014.07.15	OK
14	Thirteenth Change	2014.07.15	OK
15	Fourteenth Change	2014.07.15	OK
16	Fifteenth Change	2014.07.15	OK
17	Sixteenth Change	2014.07.15	OK
18	Seventeenth Change	2014.07.15	OK
19	Eighteenth Change	2014.07.15	OK
20	Nineteenth Change	2014.07.15	OK
21	Twentieth Change	2014.07.15	OK

5. Product:

6. report

