

□□A380□□□LED□□

Inspection Report

Report No.: XYS-130717
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYS-130717 Item No.XY-2524960 | Inspection Result: PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|----------------|---------------|--------------|---------------------|-----------------|
| XY-2524960 | 1000PCS | 5% inspection | 0pcs | No failure | 1000pcs |

| |
|--|
| Appearance Inspection : |
| No failure, |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|--|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. Product: |

| | |
|-------------------|----------------|
| 品名 | ADC12 A380 OEM |
| 品番 | ADC12 A380 |
| 仕様 | |
| 数量 | |
| 単位 | |
| 材質 | |
| 公差 | +/-0.01 |
| 表面処理 | T / T 50 |
| 検査方法 | |
| 納入期 | |
| 梱包 | |
| 備考 | |
| 1.Name | ADC12 A380 |
| 2.Process | |
| 3.品番 | ADC12 A380 |
| 4.公差 | +/-0.01 |
| 5.Tolerance | +/-0.01 |
| 6.表面処理 | T / T 50 |
| 7.Specification | |
| 8.検査方法 | |
| 9.付属品 | accessories |
| 10.納入期 | |
| 11.&NBSP;ISO 9001 | |
| 備考 | |
| 1. 10 | |
| 2. | |
| 3. kinds | available |
| 4. | |
| 5. | |
| 6. | |
| 7. | |
| 備考 | |
| &NBSP; | |
| ISO9001 | |
| OEM | |