XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYSK-140516 **Inspection Date:** 18th Jun, 2014
Supplier : **XY-GLOBAL** **Inspector:** Leo

Inspection only for:	**Inspection Result:**
PO . XYSK-140516 Item No. XY11WD017	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD017	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:



6. Dimensions report

[illegible]	[illegible]OEM[illegible]
[illegible]	[illegible]ADC12[illegible]A380[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible] [illegible]
[illegible]	[illegible] [illegible]
[illegible]	[illegible]
[illegible]/[illegible]	+/-0.01[illegible]
[illegible]	[illegible]50[illegible]50[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]50[illegible]25[illegible]
[illegible]	[illegible]
1.[illegible] [illegible]	
2.[illegible] [illegible]	
3.[illegible]ADC12[illegible]A380[illegible]	
4.[illegible] [illegible]	
5.[illegible]±0.01[illegible]	
6.[illegible]100[illegible]	
7.[illegible]	
8.[illegible]25-30[illegible]	
9.[illegible] [illegible]	
10.[illegible]	
11.[illegible]ISO 9001	
[illegible]	
1.10[illegible]ISO[illegible]	
2.[illegible]	
3.[illegible]	
4.[illegible]	
5.[illegible]	
6.[illegible]	
7.[illegible]	
[illegible]	
[illegible]	
[illegible]	
[illegible]ISO9001	
[illegible]	
[illegible]OEM[illegible]	