

**Inspection Report**

**Report No.:** XYLA-140314  
**Supplier :** XY-GLOBAL

**Inspection Date:** 8<sup>th</sup> Apr, 2014  
**Inspector:** Leo

Inspection only for: PO . XYLA-140314 Item No. 1400382	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400382	45000PCS	1% inspection	0pcs	No failure	45000PCS

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

