

**Inspection Report**

**Report No.:** XYN-140603  
**Supplier :** XY-GLOBAL

**Inspection Date:** 1<sup>st</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYN-140603 Item No.202034	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
202034	30000PCS	1% inspection	0pcs	No failure	30000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product::
	
5. Product:	6. Report:

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
加工	&NBSP;加工品
加工	加工品
加工	CNC加工品
加工	加工品 gague
加工	加工品
加工	+/-0.01
加工	T / T 50 50 T / T
加工	加工品
加工	加工品
加工	加工品
加工	T / T 50 20-25 &NBSP;
加工	加工品
1.Name 加工品cnc	
2.Process 加工品	
加工品 AL6061 AL6065 AL6063 AL7075	
4.加工品	
5.Tolerance 加工品 ±0.01	
6.加工品 100	
7.Specification 加工品 serice	
8.加工品 25-30	
9.加工品 CNC 加工品 accessoried	
10.加工品 Austrial	
11&NBSP; 加工品 ISO 9001	
加工品	
1.加工品 ISO	
2.加工品	
3.加工品 kinds available	
4.加工品	
5.加工品	
6.加工品	
7.加工品	
加工品	
&NBSP; 加工品	
加工品	
加工品 ISO9001	
加工品	
加工品	