

Inspection Report







Report No.: XYK-130825
 Supplier : XY-GLOBAL

Inspection Date:19th Sep-, 2013
 Inspector:LEO

Inspection only for: PO . XYK-130825 Item No.1412790	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1412790	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Packing:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

