

Inspection Report







Report No.: XYBA-140924
Supplier : XY-GLOBAL

Inspection Date: 20th Oct., 2014
Inspector: LEO

Inspection only for: PO . XYBA-140924 Item No. XY21ZC017	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC017	2000pcs	7% inspection	0pcs	No failure	2000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	ステンレス CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	円筒
寸法	外径φ100mm 長さ100mm
公差	±0.05mm
表面処理	鏡面研磨
検査	寸法検査 表面検査
納期	約1週間
単位	個
重量	約1.5kg
梱包	緩衝材入り
備考	
1. 品名	ステンレス CNC加工品
2. 材質	AL6061 AL6065 AL6063 AL7075
4. 寸法	外径φ100mm 長さ100mm
5. 公差	±0.01mm
6. 表面処理	鏡面研磨
7. 検査	寸法検査 表面検査
8. 納期	約25-30日
9. 単位	個
10. 重量	約1.5kg
11. 梱包	ISO 9001
品名	
1.10. 品名	ステンレス ISO加工品
2. 材質	AL6061 AL6065 AL6063 AL7075
3. 寸法	外径φ100mm 長さ100mm
4. 公差	±0.05mm
5. 表面処理	鏡面研磨
6. 検査	寸法検査 表面検査
7. 納期	約1週間
品名	
品名	ステンレス ISO加工品
品名	ステンレス ISO9001
品名	ステンレス ISO加工品
品名	OEM加工品