



Inspection Report

Report No.: XYK-131014
Supplier : XY-GLOBAL

Inspection Date: 5th Nov-, 2013
Inspector:ALEX

Inspection only for: PO . XYK-131014 Item No.XY-CT-D-046	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-046	20000PCS	0.1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.






Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	品名: 品名 CNC 品名 CNC 品名 CNC
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
数量	
単位	
加工	CNC
加工	gague
加工	
公差	+/-0.01
公差	T / T 50 50 T / T
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name 品名 cnc	
2.Process	
品名 AL6061 AL6065 AL6063 AL7075	
4.品名	
5.Tolerance ±0.01	
6.品名 100	
7.Specification serice	
8.品名 25-30	
9.品名 accessored	
10.品名 Austrial	
11&NBSP; ISO 9001	
品名	
1.品名 ISO	
2.品名	
3.品名 kinds available	
4.品名	
5.品名	
6.品名	
7.品名	
品名	
品名 &NBSP; 品名	
品名	
品名 ISO9001	
品名	
品名	