

Inspection Report

Report No.: XYDN-140617
 Supplier : XY-GLOBAL

Inspection Date: 12th July, 2014
 Inspector: Leo

Inspection only for: PO . XYDN-140617 Item No.300476	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
300476	1000PCS	1% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	
数量	
単位	
仕様	
公差	±0.01
表面処理	50μm
検査	
納期	
備考	
1. CNC加工品	
2. 加工品	
材質 AL6061 AL6065 AL6063 AL7075	
4. 公差 ±0.01	
5. 公差 ±0.01	
6. 公差 100	
7. 公差	
8. 公差 25-30	
9. 公差	
10. 公差	
11. ISO 9001	
品名	
1.10 ISO	
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
品名	
公差	
公差	
公差 ISO9001	
公差	
OEM	