

□□□□□mechanical□□

Inspection Report

Report No.: XYS-140213 -V1
Supplier : XY-GLOBAL

Inspection Date: 7th Mar-, 2014
Inspector: LEO

Inspection only for: PO . XYS-140213	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
BOTTOM	163PCS	100% inspection	0pcs	No failure, good condition	163pcs
TOP	163PCS	100% inspection	0pcs	No failure, good condition	13pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Packing
	
3. Packing	4. Product:BOTTOM
	
7 Product:TOP	8. Product: TOP
	
11Product:TUBE	12 Product:TUBE

項目	ADC12A380 OEM
品名	ADC12A380
仕様	
数量	
単位	
公差	+/-0.01
材料	T / T 50
備考	
1.Name	
2.Process	
ADC12A380	
4.公差	
5.Tolerance	±0.01
6.数量	100
7.Specification	serice
8.材料	25-30
9.accessories	
10.Austrial	
11. ISO 9001	
備考	
1. ISO	
2.	
3. kinds	available
4.	
5.	
6.	
7.	
備考	
ISO9001	
OEM	