

Inspection Report

Report No.: XYSL-140608
 Supplier : XY-GLOBAL

Inspection Date: 5th Jul, 2014
 Inspector: Leo

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYSL-140608 Item No. XY11WD032 | <u>Inspection Result:</u> PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY11WD032 | 10000PCS | 5% inspection | 0pcs | No failure | 10000pcs |

| |
|--|
| Appearance Inspection : |
| No failure, |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. The test report |

